



254 Thames Road East Exeter, ON. N0M-1S3
 (519) 235-1431 / 1-866-335-1431
 Email: sales@exacon.ca www.exaconinc.ca

**L.B. WHITE GUARDIAN FORCED AIR HEATERS
 (GUARDIAN AND GUARDIAN 2.0 MODEL REPLACEMENT PARTS)
 *PLEASE CONTACT US FOR PRICING AND AVAILABILITY**

60					
Description	Guardian 1.0	Existing Part #	Guardian 2.0	New Part#	Interchangeable
Igniter (HSI)	573659	E78-0434	573659	E78-0434	Yes
Motor	520290	E67-3900	520290	E67-3900	Yes
Fan (Blower Wheel)	570230	E67-3921	570230	E67-3921	Yes
Gas Valve LP	522076	E67-3172	573774	E78-0464	No
Gas Valve NG	522078	E67-3173	573773	E78-0465	No
Igniter (SI)	573165		574196	E78-0435	No
Flame Sensor	572412	E78-0408	574284	E78-0413	No
Hi Limit	503933	E78-0470	572501	E78-0478	No
Transformer	509615	E67-3902	574289	E78-0481	No
Control Board (SI)	524900	E67-3850	574287	E78-0487	No
Control Board (HSI)	509298	E67-3934	574288	E78-0483	No
New Air Diverter			500-133427	E78-0040	

HSI= Hot Surface Ignition SI= Spark Ignition

100					
Description	Guardian 1.0	Existing Part #	Guardian 2.0	New Part#	Interchangeable
Igniter (HSI)	573659	E78-0434	573659	E78-0434	Yes
Motor	520292	E78-0480	520292	E78-0480	Yes
Fan (Blower Wheel)	570304	E78-0485	570304	E78-0485	Yes
Gas Valve LP	522076	E67-3172	573774	E78-0464	No
Gas Valve NG	522078	E67-3173	573773	E78-0465	No
Igniter (SI)	570021	E78-0406	574196	E78-0435	No
Flame Sensor	572412	E78-0408	574284	E78-0413	No
Hi Limit	503933	E78-0470	573099	E78-0479	No
Transformer	573724	E67-3902	574289	E78-0481	No
Control Board (SI)	524900	E67-3850	574287	E78-0487	No
Control Board (HSI)	509298	E67-3934	574288	E78-0483	No
New Air Diverter			500-133428	E78-0041	

HSI= Hot Surface Ignition SI= Spark Ignition

250 BTU AND GUARDIAN 2.0 REPLACEMENT PARTS ON NEXT PAGE

All prices and availability are subject to change without notice due to supplier increases, market conditions, fuel costs, exchange rate fluctuations, and other economic factors; please contact our office for a current quotation to confirm pricing



254 Thames Road East Exeter, ON. N0M-1S3
 (519) 235-1431 / 1-866-335-1431
 Email: sales@exacon.ca www.exaconinc.ca

**L.B. WHITE GUARDIAN FORCED AIR HEATERS
 (GUARDIAN AND GUARDIAN 2.0 MODEL REPLACEMENT PARTS)
 *PLEASE CONTACT US FOR PRICING AND AVAILABILITY**

250					
Description	Guardian 1.0	Existing Part #	Guardian 2.0	New Part#	Interchangeable
Igniter (HSI)	573659	E78-0434	573659	E78-0434	Yes
Motor	520169	E67-3903	520169	E67-3903	Yes
Fan (Blower Wheel)	570481	E78-0421	570481	E78-0421	Yes
Gas Valve LP	522076	E67-3172	573774	E78-0464	No
Gas Valve NG	522078	E67-3173	573773	E78-0465	No
Igniter (SI)	570021	E78-0406	574196	E78-0435	No
Flame Sensor	520139	E78-0409	574284	E78-0413	No
Hi Limit	505566	E67-3904	573099	E78-0479	No
Transformer	509615	E67-3902	574289	E78-0481	No
Control Board (SI)	524900	E67-3850	574287	E78-0487	No
Control Board (HSI)	509298	E67-3934	574288	E78-0483	No
New Air Diverter			500-133429	E78-0042	

HSI= Hot Surface Ignition SI= Spark Ignition

LB WHITE HEATER REPLACEMENT PARTS

* HSI (HOT SURFACE IGNITION)

* SI (SPARK IGNITION)

EXACON PART #	LBW MOD#	DESCRIPTION
E78-0413	574284	2.0 FLAME SENSOR AW60-250 HSI
E78-0464	573774	2.0 GAS VALVE 24V L.P. HSI/SI
E78-0465	573773	2.0 GAS VALVE 24V N.G. HSI/SI
E78-0478	572501	2.0 HI LIMIT SWITCH 240° AW60
E78-0479	573099	2.0 HI LIMIT SWITCH AW100/250
E78-0481	574289	2.0 TRANSFORMER AW60/100/250

All prices and availability are subject to change without notice due to supplier increases, market conditions, fuel costs, exchange rate fluctuations, and other economic factors; please contact our office for a current quotation to confirm pricing